

Ivanhoe North



Centennial Coal



Annual Environmental Management Report

2013

Ivanhoe North Lagoon Rehabilitation Works Completed (2013)

Name of mine	Ivanhoe North Colliery		
Titles/Mining Leases	ML1627		
MOP Commencement Date	17/03/2012	MOP Completion Date	17/03/2019
AEMR Commencement Date	01/01/2013	AEMR End Date	31/12/2013
Name of Leaseholder	Ivanhoe Coal Pty. Ltd.		
Name of mine operator (if different)			
Reporting Officer	Tom Hollis		
Title	Environment and Community Officer		
Signature	_____		
Date			

Contents

1. Introduction	5
1.1 Consents, Leases and Licences	5
1.2 Mine Contacts	7
1.3 Actions Required at Previous AEMR Review	7
2. Operations During the Reporting Period	8
2.1 Exploration	8
2.2 Land Preparation.....	8
2.3 Construction	8
2.4 Mining.....	8
2.5 Mineral Processing.....	8
2.6 Waste Management.....	8
2.7 Product Stockpiles	8
2.8 Water Management.....	8
2.8.1 Stored Water	8
2.9 Hazardous Material Management.....	8
3. Environmental Management and Performance.....	9
3.1 Meteorological Data	9
3.1.1 Rainfall	9
3.2 Air Quality.....	9
3.3 Erosion and Sediment Management.....	9
3.4 Surface Water Quality	10
3.4.1 Monitoring and Performance Criteria	10
3.4.2 Results LDP001, LDP002 and LDP006	10
3.5 Ground Water Quality	12
3.6 Threatened Flora and Fauna	12
3.7 Weeds	12
3.9 Blasting.....	12
3.10 Operational Noise	12
3.11 Visual or Stray Light	12
3.12 Aboriginal Heritage.....	12
3.12.1 European Heritage	12
3.13 Spontaneous Combustion.....	12
3.14 Bushfire	12
3.15 Mine Subsidence.....	13
3.16 Contaminated Land Management.....	13
3.16.1 Phase 1 Environmental Site Assessment	13

3.17 Methane Drainage.....	13
3.18 Public Safety	13
3.19 Other Issues and Risks	13
3.19.1 Risk Management	13
4. Community Relations	15
4.1 Environmental Complaints	15
4.2 Community Liaison.....	15
4.2.1 Celebrate Lithgow	15
4.2.2 National Aboriginal and Islander Day Observance Committee (NAIDOC) Celebrations.....	15
5. Rehabilitation	16
5.1 Buildings.....	16
5.2 Rehabilitation of Disturbed Land	16
5.3 Rehabilitation Monitoring.....	19
6. Activities Proposed in the Next AEMR Period	23

Figures

Figure 1. Contour bank structure installation during the reporting period.....	11
Figure 2. Preliminary Sediment Dam 1B: resizing work during the reporting Period.....	11
Figure 3. Centennial Representatives at Celebrate Lithgow Street Fair (left) and Hartley NAIDOC Celebrations (right).....	15
Figure 4. Rehabilitation Area in Southern Blocks	17
Figure 5. Rehabilitation in Northern Block	17
Figure 6. Rehabilitation in Central Block.....	17
Figure 7. Monitoring Transect Locations at Ivanhoe North Colliery.....	20

Tables

Table 1. Ivanhoe North Colliery Licences, Consents and Approvals.....	6
Table 2. Contact Details for Key Mine Personnel	7
Table 3. Actions Required at Previous AEMR Review	7
Table 4. Stored Water	8
Table 5. Monthly Rainfall.....	9
Table 6. Dust Deposition Monitoring 2013.....	9
Table 7. LDP001, LDP002 and LDP006 EPL Limits.....	10
Table 8. LDP001 Water Quality Monitoring Results	10
Table 9. Risk Identification Matrix	14
Table 10. Rehabilitation Summary.....	18
Table 11. Maintenance Activities on Rehabilitated Land – Ivanhoe North	19
Table 12. Study Transects of Rehabilitation Monitoring Program	20

Appendices

Appendix 1	Ivanhoe North Rehabilitation Project AEMR Plans
Appendix 2	Environment Protection Licence No. 13063 - Ivanhoe North

1. Introduction

The area within Ben Bullen State Forest on which Mining Lease (ML) 1627 is located, has been the subject of previous coal mining, and mining related operations. This includes the Cullen Main West open cut mining operations completed in the years following World War II and more recently mine ventilation and mine waste disposal for the Ivanhoe and Invincible Collieries (**Plan 2**).

The Cullen Main West open cut was a contour mining operation which operated shortly after World War II. The open cut which is situated immediately to the northwest of Ivanhoe Colliery's No.2 underground workings was abandoned following the cessation of mining in the early 1950s. Ivanhoe Coal Pty Limited has used approximately 20% (2.0 ha) of the abandoned open cut for mine ventilation for the Ivanhoe Colliery and placement of coarse reject generated by the Ivanhoe and Invincible Collieries. The ventilation fan has subsequently been removed.

Centennial obtained development consent to extract the remaining coal reserves and rehabilitate the old mining areas on ML 1627. The project commenced on 8th July 2009 and was completed in May 2012. The project represents the utilisation of an available coal resource while at the same time providing an opportunity to rehabilitate an otherwise derelict mine site.

Coal extraction ceased on 26 March 2012 and the last coal was transported off site on 26 April 2012.

The INRP targeted the coal remaining between the remnant high wall of the Cullen Main West open cut and the underground workings of Ivanhoe Colliery No. 2. In recommencing mining operations from the abandoned open cut, Ivanhoe Coal Pty Ltd inherited responsibility for the rehabilitation of the previous disturbance within the mining lease. Rehabilitation obligations for the majority of the mining-related disturbance (80% or 11.4 ha) previously resided with the NSW Government.

The Project included:

- Construction of all surface infrastructure including a site access road and intersection with the Castlereagh Highway, Coal Crushing Area, Facilities Area, and water storage and water management structures;
- Land preparation including vegetation clearing and soil stripping;

- Removal of overburden and interburden materials to expose the Irondale, Lidsdale and Lithgow Coal Seams;
- Mining of the exposed coal of the Irondale, Lidsdale and Lithgow seams;
- Crushing of the mined coal to reduce the size of the coal;
- Progressive backfilling, profiling and rehabilitation of mined out sections of the open cut using the overburden and interburden previously removed; and
- Transportation of the crushed coal via the mine access road and Castlereagh Highway. Based on the proposed production of 300 000 tonnes of coal per year, an average of 35 trucks would be despatched each day, although this is expected to vary between 0 and approximately 50 per day, to complement the campaign crushing operations.

This Annual Environmental Management Report (AEMR) relates solely to the INRP and covers the reporting period 1 January 2013 to 31 December 2013.

The project has now commenced final closure rehabilitation activities.

This AEMR details the final mining activities prior to completion and rehabilitation activities for the INRP during the reporting period.

1.1 Consents, Leases and Licences

Ivanhoe Coal Pty Limited own and operate the Ivanhoe North Rehabilitation Project (INRP), which commenced operation in 8th July, 2009. The Project operates under the Environmental Protection Licence (EPL 13063) and Development Consent (DA_05_0103) (**Appendix 2**).

A meeting was held with the EPA regarding modifications to the EPL and discussions will be ongoing during the coming reporting period. No modifications were made to the EPL during the reporting period.

The Project Approval (05_0103) was granted by the then Department of Planning on 11 April 2007. A Modification to the Project Approval (05_0103) was sought under Section 75W of the Environmental Planning and Assessment Act 1979 (EP&A Act). The modification allowed for an extension of the Project Approval from 2 February 2012 until 2 May 2012 to complete mining and trucking operations in a safe and efficient manner. The approval for the continuation of mining operations was received on 19 January 2012.

Open Cut Mining is permissible under ML 1627 which incorporates MPL 79 in its entirety, creating a single mining tenure. MPL 79 is a previous Ivanhoe Coal Pty Limited surface lease of 12.2 ha.

The current MOP covers the final rehabilitation of the project for the period ending 17 March 2019. The MOP was updated during the reporting period to include recent water management structures and submitted to Greg Kininmonth and Craig Campbell in November 2013.

Ivanhoe Coal Pty Ltd holds Environmental Protection Licence (EPL) 13063 under the Protection of the Environment Operations Act 1997 (**Appendix 2**). The licence has an Anniversary date of the 24th of April each year

and covers 3 surface water discharge points and 3 dust monitoring points (Error! Reference source not found.).

The Stream 3 Restoration Management Plan was approved by the NSW Office of Water on 1 March 2011.

In addition to the current MOP the site operates under a Rehabilitation and Mine Closure Plan which was completed in consultation with Department of Trade and Investment, Regional Infrastructure and Services (DTIRIS) and Office of Environment and Heritage (OEH), and approved by the Department of Planning and Infrastructure (DP&I).

Table 1. Ivanhoe North Colliery Licences, Consents and Approvals

Licence/Approval/Consent	Approval/Number	Approval Authority	Date Granted-Expiry/Renewal Date
Development Consents			
Original Development Consent	DA_05_0103	Department of Planning & Infrastructure	Approved 11/04/2007
Development Consent Modification	DA-05_0103	Department of Planning & Infrastructure	Approved 19/01/2012
Licences			
Environmental Protection Licence	EPL13063	Environment Protection Authority	02/07/2013-Renewed Annually 24 th of April
Consolidated Coal Lease	CCL712	Department of Trade and Investment, Regional Infrastructure and Services	18/06/1989-Perpetuity
Mining Lease	ML1627	Department of Trade and Investment, Regional Infrastructure and Services	17/03/2009-17/03/3030
Mining Purposes Lease	MPL79	Department of Trade and Investment, Regional Infrastructure and Services	21/07/1994-21/07/2015
Mining Operations Plan			
Mining Operations Plan	N/A	Department of Trade and Investment, Regional Infrastructure and Services	17/03/2012-17/03/2019

1.2 Mine Contacts

Table 2. Contact Details for Key Mine Personnel

Name	Title	Phone
Bob Miller	Mine Manager	02 63592101
Tom Hollis	Environment and Community Officer	02 6355 9810

1.3 Actions Required at Previous AEMR Review

The 2012 AEMR was reviewed by relevant government agencies and an onsite inspection was completed on 28 Aug 2013 with DTIRIS, OEH, Lithgow City Council and Centennial representatives. A letter was received from DTIRIS dated 29 October 2013 raising a number of issues and actions to be completed by 30 November 2013. A summary of actions identified at the 2012 AEMR review and feedback from the DTIRIS is presented in **Table 3**.

Table 3. Actions Required at Previous AEMR Review

Action Required	Where dealt with in this AEMR
Continuation of rehabilitation monitoring at Ivanhoe North Ongoing using the LFA assessment tool.	Section 5.3.
Continue site maintenance (weed spraying, erosion and sediment controls).	Section 3.4 and Section 3.7.
Addition of soil ameliorants on the rehabilitated areas where required in accordance with the SESL report.	Section 5.3.1.2.
Continue consultation with stakeholders regarding rehabilitation and mine closure at Ivanhoe North.	Section 4.
Continued consultation with OEH regarding modifications to the EPL.	Section 1.1.
Update the current MOP to include recent water management structures.	Section 1.1.

2. Operations During the Reporting Period

2.1 Exploration

No exploration was carried out for the INRP during the reporting period. The coal resource geology is well understood and it is not anticipated that any exploration will be undertaken during the term of the Project.

2.2 Land Preparation

No mining was undertaken during the reporting period therefore no land preparation occurred. There was minor earth moving activities during the reporting period mainly associated with surface water diversion for erosion and sediment control purposes.

2.3 Construction

No construction work was required during the reporting period.

2.4 Mining

There was no mining production or waste generation during this reporting period.

2.5 Mineral Processing

Coal processing infrastructure was removed and the area rehabilitated during the 2012 reporting period.

2.6 Waste Management

The mine did not produced any coal or reject material during the reporting period.

2.7 Product Stockpiles

No run-of-mine (ROM) or product coal stockpiles remain onsite.

2.8 Water Management

The Site Water Management Plan prepared by GHD in 2010 has been implemented. The primary aim of the plan is the effective separation of clean and dirty water. This included the construction of clean water diversion channels and ponds as well as appropriate dirty water containment structures as described in the following sections. These structures will remain until rehabilitation work is self-sustaining and the landform considered stable, and therefore no longer required.

There are three clean catchments which are controlled upstream of the mine area. Water from these catchments is directed via channels and embankments into three clean water dams

(Plan 6). Drainage from the now rehabilitated mine area is directed into sediment ponds as described below:

- *Dirty water* - this generally comprises stormwater runoff generated in disturbed areas such as the previous open cut and overburden emplacement and rehabilitated areas. This water has the potential for contamination from sources such as sediment and coal fines; and
- *Clean water runoff* - this comprises runoff from undisturbed parts of the surrounding catchments.

All attempts are made to capture and divert clean water runoff around the site to avoid contamination and reduce pressure on the dirty water management system. The volume of dirty water to be treated is therefore minimised by both limiting the contamination of clean water and through maximising the re-use of dirty water for dust suppression and other water requirements as necessary.

2.8.1 Stored Water

The stored water at the beginning and end of the reporting period are presented in **Table 4**. It should be noted that these values are estimates only.

Table 4. Stored Water

	Volumes held (ML)		
	Start of Reporting Period	At end of Reporting Period	Storage Capacity
Clean Water			
CWD 1	0.35	0.15	0.5
CWD 2	0.15	0.05	0.25
CWD 3	0.30	0.05	1
Dirty Water			
SD 1-A	2.10	0.5	2.25
SD 1-B	0.1	0.1	1.0
SD 2	0.45	0.2	1.2
SD 3	0.15	0.1	0.25
Contaminated Water	0	0	

2.9 Hazardous Material Management

No hazardous materials have been stored on site since site has moved into the rehabilitation stage.

3. Environmental Management and Performance

This section summarises environmental management throughout the 2013 reporting period at Ivanhoe North Colliery.

3.1 Meteorological Data

Meteorological data is sourced from a weather station located at the Pinedale Mine which is located in close vicinity to the site.

3.1.1 Rainfall

The monthly rainfall fluctuates throughout the year, with the highest rainfall occurring in February and the minimum occurring in October. Total annual rainfall for 2013 was 576.6mm (**Table 5**).

As part of the automatic water sampling equipment and real time monitoring a tipping bucket rain gauge has been installed at Sediment Dam 3.

Table 5. Monthly Rainfall

Month	Rainfall (mm)
January	94.4
February	131.2
March	31.6
April	27
May	22.6
June	79.2
July	18.2
August	18.2
September	44.4
October	15
November	59.4
December	35.4
Total	576.6

3.2 Air Quality

Deposited dust levels are required by EPL 13063 to be monitored monthly at three dust deposition gauge monitoring sites.

The EPL monitoring sites are:

- INDD-C: located approximately 460 m northwest of the closest activities on the mine site;
- INDD-G: located 1200 m southwest of the closest activities on the mine site; and
- INDD-K: located approximately 420 m north of the closest activities on the mine site.

Dust monitoring first commenced at the site in June 2009.

Dust depositional results indicate average dust levels remained low across all sites with results only 2 results at INDD-G recording two elevated results in July and August. INDD-C and INDD-K results remained low during the 2013 reporting period. Dust results show monthly dust levels were generally below the 4g/m²/month at all gauges with the exception of INDD-G as mentioned above. Long term dust depositional gauge monitoring results indicates the site is producing minimal dust, with annual averages at all Dust Monitoring sites all well below 2 g/m²/month (**Table 6**)

Table 6. Dust Deposition Monitoring 2013

Date Collected	INDD-C (g/m ² /month)	INDD-G (g/m ² /month)	INDD-K (g/m ² /month)
15-Jan-13	2.2	0.9	1.0
15-Feb-13	0.6	0.8	0.8
15-Mar-13	0.5	0.7	0.8
15-Apr-13	0.6	0.8	2.9
13-May-13	1.9	0.2	0.4
11-Jun-13	0.8	2.1	0.6
11-Jul-13	0.9	10.2	0.4
09-Aug-13	1.1	5.4	BD
09-Sep-13	0.4	0.2	1.3
11-Oct-13	0.4	BD	BD
12-Nov-13	2.2	0.7	0.6
13-Dec-13	1.7	1.8	3.2
Annual Average	1.1	1.8	1.2

3.3 Erosion and Sediment Management

Erosion and sediment is managed at the INRP through the Erosion and Sediment Control Plan, which forms part of the Revised Site Water Management Plan (Revised SWMP). The Erosion and Sediment Control Plan is a requirement of Schedule 3, Condition 10 of DA 05_0103, and is in accordance with the guideline document "Managing Urban Stormwater: Soils and Construction Manual 2004".

During the reporting period, several erosion and sediment control strategies were implemented or maintained. These included:

- Mid-slope contour banks aiming to increase infiltration and trap sediment by catching surface runoff and slowing the flow;
- A series of small sediment traps within the new contour system pools runoff water and settles coarse sediment;
- The preliminary sediment dam upstream of Lilley's Dam SD1, was resized to comply with Blue Book Type D/F Basin Standards (3.5ML total capacity) and incorporates a small diversion and gentle spill way directing the water away from existing erosion areas and into established grass lands before the water enters in to Lilley's Dam.
- Management of soil resources as per the erosion and sediment control guidelines (e.g. correct soil stripping);
- All internal roads have been constructed to ensure surface drainage is optimised and stabilised, thereby reducing roadside erosion and sedimentation;
- Clean water dams and diversion works have been established;
- Dirty water capture from disturbed areas;
- Maintenance of erosion and sediment control structures such as silt fences and hay bales; and
- Use of flocculation in select sediment dams.

3.4 Surface Water Quality

Surface water monitoring is undertaken in accordance with the sites Surface Water Monitoring Program. This forms part of the Revised SWMP.

Ivanhoe North has three licensed surface water discharge points.

- LDP001 (point 1) – Overflow from Sediment Dam 1 (SD-1);
- LDP002 (point 2) - Overflow from Sediment Dam 2 (SD-2); and
- LDP006 (point 6) – Overflow from Sediment Dam 3 (SD-3).

3.4.1 Monitoring and Performance Criteria

Ivanhoe North monitors surface water discharge from its licenced discharge points LDP001, LDP002 and LDP006 (**Plan 4**) according the conditions set out in Environmental Protection Licence (EPL) 13063 (**Appendix 2**). The criteria for discharge water quality are outlined in **Table 7**.

Table 7. LDP001, LDP002 and LDP006 EPL Limits

Parameter	EPA Licence Limit
pH	6.5-8.5
Total Suspended Solids (mg/L)	30
Oil and Grease (mg/L)	10

3.4.2 Results LDP001, LDP002 and LDP006

Three controlled discharges occurred during January and February. These treatment and release events were done to prevent uncontrolled discharge from Sediment Dam 1 following significant rain events that occurred late in December 2012 and continued in January and February 2013. Water quality results are outlined in **Table 8**. No discharges were recorded from LDP002 and LDP006. Discharge Volumes for January totalled 1.2ML, and February totalled 4.2ML.

Table 8. LDP001 Water Quality Monitoring Results

Date of Sample	Minimum pH	Minimum TSS (mg/L)	Minimum Oil and Grease (mg/L)
Jan-13	6.89	10	<5
Feb-13	6.51	8	<5



Figure 1. Contour bank structure installation during the reporting period



Figure 2. Preliminary Sediment Dam 1B: resizing work during the reporting Period

3.5 Ground Water Quality

As reported in previous AEMRs the project had a low risk of impacting groundwater and no groundwater dependent ecosystems were identified during the original environmental assessment process. Now that that coal extraction and processing has ceased, the ongoing rehabilitation activities have an even lower risk.

There are no hydrocarbon storages on site and no specific groundwater controls or protection measures are required.

3.6 Threatened Flora and Fauna

Current and future rehabilitation activities within the Ivanhoe Colliery sites will promote a positive impact on local flora and fauna including improving habitat value and diversity and overall biodiversity.

With all mining complete and rehabilitation continuing to improve, no adverse impacts are predicted to threatened flora or fauna.

3.7 Weeds

The Ivanhoe North Environment and Community Coordinator inspects the land holding for any noxious weeds such as Blackberry, St Johns Wort, Spear Thistle, Cudweed and Catsear. The site rehabilitation work is low in weed distribution and abundance. Weeds are actively managed as detected and recorded upon site inspections and are dealt with accordingly. Weed control measures for the INRP include:

- Weeds are recorded as part of monthly inspection and an annual weed management survey is completed; and
- Minor weed spraying is completed.

3.9 Blasting

With operations completed at Ivanhoe North Colliery, there has not been any blasting activities during the reporting period.

3.10 Operational Noise

Noise generation at the Ivanhoe North Colliery has been minimal during the reporting period, as the mine has remained on care and maintenance. Noise produced is usually limited to the occasional use of light vehicles during regular inspections of the mine and the use of equipment to update the sites erosion and sediment control system. Work has only been completed on a Monday to Friday and during daylight hours basis.

3.11 Visual or Stray Light

All operations are completed at Ivanhoe North Colliery, therefore visual and stray light is not considered a problem.

3.12 Aboriginal Heritage

OzArk Environmental and Heritage Management Pty Limited (Ozark) was commissioned to identify any artefacts or sites of Aboriginal heritage significance on the project site for the 2006 EA.

A search of the Aboriginal Heritage Information Management System (AHIMS) – Aboriginal Sites Register within a 10 km square area centred on the project site identified a total of 71 recorded sites. No Aboriginal artefacts or sites were identified during a field survey by OzArk's archaeologists and the Bathurst Local Aboriginal Land Council representative.

As no Aboriginal sites or artefacts were identified on the project site, no specific safeguards or management practices were proposed. However, site employees and contractors were advised of their responsibilities under the National Parks and Wildlife Act 1974 to immediately cease work in the vicinity of any identified or suspected site or artefact until such time as the management of the site/artefact has been discussed with a NSW Office of Environment and Heritage archaeologist, and a representative of the Bathurst Local Land Aboriginal Council.

As part on the induction process, all employees were required to undertake cultural awareness training to understand their responsibilities in regard to aboriginal artefacts.

3.12.1 European Heritage

There are no identified items of European heritage within the mining lease.

3.13 Spontaneous Combustion

There were no issues of spontaneous combustion during the reporting period.

3.14 Bushfire

The project site is characterised by open forest and woodland vegetation, dominated by Eucalyptus tree species and a relatively open sub-strata of shrubs and grasses. A bushfire hazard exists due to the vegetation type, with this hazard increasing during the warmer summer months and decreasing over the cooler winter months.

A Bushfire Management Plan has been developed and approved for the site by Forests NSW. The Bushfire Management Plan outlines:

- Emergency procedures and numbers;
- Firefighting equipment;
- Management of flammable materials;
- Training; and
- Water Sources for firefighting.

There was a small bushfires within the mining lease during the reporting period. The fire started during a storm when lightning caused a small fire to start and continue to smoulder in the Ben Bullen State Forest to the south of Ivanhoe North. Rural Fire Trucks accessed the fire via entry through Ivanhoe North. A helicopter was brought in to control the small blaze and filled from a neighbouring farm dam as dam levels at Ivanhoe North did not suffice.

3.15 Mine Subsidence

No subsidence has been identified during the reporting period. Any subsidence identified during inspections will be recorded and appropriately remediated.

3.16 Contaminated Land Management

3.16.1 Phase 1 Environmental Site Assessment

A Phase 1 Environmental Site Assessment (ESA) was completed in 2010 at Ivanhoe North. The report considered potential moderate to low risk of contamination at Ivanhoe North, although no contamination was identified. Further investigations will occur prior to lease relinquishment.

3.17 Methane Drainage

Not applicable.

3.18 Public Safety

The following controls have been implemented for the INRP to manage public safety:

- Access to the mining lease is restricted to authorized personnel only. Security gates have been installed near the Castlereagh Highway intersection and are locked at all times;

- Security/warning signs on security gates;
- Employee inductions in safe working practices and regular follow-up safety meetings and reviews will be undertaken;
- All mobile equipment are compliant with the Mine Design Guideline (MDG) 15 fitted with appropriate safety and fire suppression equipment; and
- All mining lease, project approval and licence conditions will be strictly complied with.

Fences were installed at site following consultation with the neighbouring land owner and Forests NSW. This includes:

- Four strand barbed-wire stock proof fence along the western boundary of the mine site adjoining the land of neighbour; and
- Six foot security fencing along the eastern boundary of the mine site (adjoining the Castlereagh Highway).

3.19 Other Issues and Risks

3.19.1 Risk Management

Environmental Management for the INRP is undertaken through a risk driven methodology. Assessing risk against predetermined consequence and probability criteria allows for site resources to be efficiently deployed toward high risk or high consequence issues.

A risk assessment was carried out as part of the MOP preparation. The completed assessment is summarised in **Table 9**.

The identification and assessment of environmental risks at the mine allowed management plans and procedures to be developed to minimise the potential risk on the environment and community. Management controls are required for all items which have been assessed as either high or medium risk.

Table 9. Risk Identification Matrix

Issue	Exploration	Land preparation, vegetation and topsoil stripping.	All construction activities including earth moving.	Mine development and mining, surface and underground.	Use/maintenance of roads, tracks and equipment.	Waste rock emplacement management.	Mineral processing facilities and infrastructure.	Ore/product stockpiling and handling.	Tailings impoundment management	Water management including storm event contingencies.	Hazardous materials and fuel, handling/spills management.	Sewerage.	Rubbish disposal.	Rehabilitation activities.	Rehabilitated land and remaining features.
Air pollution, dust/other	n/a	2	2	2	2	2	2	2	n/a	1	1	n/a	2	2	2
Erosion/ sediment minimisation	n/a	2	2	1	2	2	1	2	n/a	2	n/a	n/a	n/a	2	2
Surface water pollution	n/a	2	2	1	2	2	1	2	n/a	2	2	n/a	2	2	2
Groundwater pollution	n/a	n/a	n/a	1	n/a	n/a	n/a	n/a	n/a	1	1	n/a	n/a	n/a	n/a
Contaminated or polluted land ¹	n/a	1	1	1	1	1	1	1	n/a	1	2	n/a	1	2	2
Threatened flora protection	n/a	1	1	n/a	n/a	n/a	n/a	n/a	n/a	1	1	n/a	n/a	1	1
Threatened faun/a protection	n/a	2	1	n/a	n/a	n/a	n/a	n/a	n/a	1	1	n/a	1	1	1
Weed control and management	n/a	2	1	n/a	1	n/a	n/a	n/a	n/a	1	n/a	n/a	1	2	2
Operation/al noise	n/a	2	1	2	2	2	2	2	n/a	n/a	1	n/a	1	1	n/a
Vibration from air blast	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Visual amenity, stray light	n/a	1	1	1	1	1	1	1	n/a	1	1	n/a	1	1	1
Aboriginal heritage	n/a	1	n/a	n/a	1	1	n/a	n/a	n/a	1	n/a	n/a	n/a	1	1
Natural heritage conservation ²	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Spontaneous combustion	n/a	n/a	n/a	1	n/a	n/a	1	2	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Bushfire	n/a	2	1	1	2	1	1	1	n/a	1	2	n/a	n/a	1	2
Mine subsidence	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Hydrocarbon contamination	n/a	1	1	1	1	1	1	1	n/a	1	2	n/a	1	1	1
Methane drain/age/venting	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Public safety ³	n/a	2	2	2	2	2	2	2	n/a	1	2	n/a	1	2	2
1 = Low Impact 2 = Moderate Impact 3 = Catastrophic Impact n/a = not applicable															
Note 1: No existing contaminated or polluted land has been identified within the mine site to date.															
Note 2: The area of disturbance does not contain items of natural heritage significance.															
Note 3: All activities carry some form of risk to public safety, however, there will be no public access to these activities															

4. Community Relations

Centennial seeks to keep open communication channels with the local community. With the Ivanhoe Colliery sites on long-term care and maintenance, it is unlikely that any issues should arise in terms of complaints, incidents or environmental issues.

4.1 Environmental Complaints

During the reporting period there were no community complaints registered. Centennial has never received any community complaints for the Ivanhoe North Colliery.

4.2 Community Liaison

Although mining activities have ceased at the Colliery, Ivanhoe North representatives undertake community engagement through planned and unplanned activities outlined below.

Environmental issues associated with the rehabilitation and maintenance works are unlikely to result in impact on the surrounding community and associated complaints. Centennial manages these potential issues through implementing the various controls identified in the MOP.

4.2.1 Celebrate Lithgow

Centennial participated in the annual Celebrate Lithgow activities held in November 2013. Centennial had an information stall set up in the street fair. Representatives from each of Centennials Western Operations and Projects were available to provide information

regarding operations and environmental management at each site (**Figure 3**).

Ivanhoe North provided information regarding the recent rehabilitation activities undertaken.

4.2.2 National Aboriginal and Islander Day Observance Committee (NAIDOC) Celebrations

Centennial supplied representatives to run the BBQ during Lithgow NAIDOC celebrations held in September 2013 (**Figure 3**). The 2013 NAIDOC celebrations organized by Mingaan Aboriginal Corporation included Wiradjuri dance, Koori Sports, the Taronga Zoo mobile as well as information stalls, displays and activities.

Consultation will continue during the rehabilitation phase of the project. This is particularly important as the rehabilitation monitoring program will be used to verify the achievement of the objectives of the program and the ongoing involvement of key stakeholders is an essential component of this process.



Figure 3. Centennial Representatives at Celebrate Lithgow Street Fair (left) and Hartley NAIDOC Celebrations (right)

5. Rehabilitation

5.1 Buildings

No buildings or infrastructure remain within the Ivanhoe North Colliery.

5.2 Rehabilitation of Disturbed Land

The RMCP divides rehabilitation and closure tasks into the following procedures:

Clearing and Seed Collection Procedures

- Seed collection;
- Vegetation Clearing;
- Fauna Management;
- Salvage and Reuse of Material; and
- Conserving Soil Resources.

Rehabilitation Procedures

- Landform Preparation;
- Seeding Procedures;
- Water Management; and
- Rehabilitation Management.

Closure Procedures

- Removal of infrastructure and roads; and
- Disconnection of services.

The formation of the final landform ensured that large bulky material and rocks were kept well below the surface to prevent exposure and disturbance of the surface whilst the process of final surface preparation and revegetation was undertaken.

The final landform was created through the replacement of overburden within the completed open cut. The landform incorporated the revegetated spoil dumps of the Cullen Main West open cut and recreated the natural slope of the land prior to mining related disturbance. The final slopes vary from approximately 6° at the southern end of the final landform to approximately 14° at the northern end. No slopes exceed 18° (approximately 1V:3H). Natural drainage lines that currently traverse the abandoned Cullen Main West open cut were reinstated and the entire site revegetated with native woodland species endemic to the local area. Stream 3 was reinstated in the previous reporting period.

The conventional method of direct seeding was employed. This involved the direct application of a mix of native tree, shrub and understorey species over the surface of the prepared landform. This method involved contour ripping the surfaces as detailed above. On profiling the backfilled landform, the previously stripped top-layer material will be respread to a depth of up to 50cm. The respread top-layer will then be deep ripped on the contour to allow/assist bedding of the topdressing materials.

The principal objective of the RMCP is to create a stable landform which will pose no long-term environmental hazard. It was therefore proposed to rehabilitate Ivanhoe North to a woodland environment, similar to the native vegetation surrounding the site. The goal is for the final landform to be self-sustaining and require minimal maintenance to be undertaken.

Seed from adjacent bushland will help facilitate rehabilitation around the fringe of the land disturbed by the open cut mining process. Seed was purchased for Ivanhoe North to compensate for the shortage from seed collection at site.

The species list used reflects the native species found on the mining lease and surrounding Ben Bullen State Forest. The seed mix included a mixture of grasses, mid storey and upper storey species to create a woodland/ grassland habitat.

The major rehabilitation activities associated with the INRP are outlined in the RMCP. Rehabilitation results in areas of the southern blocks were below expectations and the investigation findings are outlined in **Section 5.4.2**.

There was no rehabilitation work undertaken during the reporting period. A rehabilitation summary and record of maintenance activities on rehabilitated land is shown in **Table 10** and **Table 11**.



Figure 4. Rehabilitation Area in Southern Blocks



Figure 5. Rehabilitation in Northern Block



Figure 6. Rehabilitation in Central Block

Table 10. Rehabilitation Summary

MINE LEASE AREA	Area Affected/Rehabilitated (hectares)			
	To Date	Last Report	Next Report (estimated)	
A1: Mine Lease(s) Area	80.2			
B: Disturbed Areas				
B1: Infrastructure area (other disturbed areas to be rehabilitated at closure including facilities, roads)	4.2	0	0	
B2: Active Mining Area, (excluding items B3-B5 below)	13.7	0	0	
B3: Waste emplacements (active/unshaped/in or out-of-pit)	7.6	0	0	
B4: Tailings emplacements, (active/unshaped/in or out-of-pit)	0	0	0	
B5: Shaped waste emplacement (awaits final vegetation)	6.7	0	0	
ALL DISTURBED AREAS	28	28	28	F1
C: REHABILITATION PROGRESS				
C1: Total Rehabilitated Area (except for maintenance)	17.6	17.6	17.6	F2
D: REHABILITATION ON SLOPES				
D1: 10 to 18 degrees	11.1	0	0	
D2: Greater than 18 degrees	4.1	0	0	
E: SURFACE OF REHABILITATED LAND				
E1: Pasture and grasses	0	0	0	
E2: Native forest/ecosystems	17.6	0	0	
E3: Plantations and crops	0	0	0	
E4: Other (include non vegetative outcomes)	0	0	0	

Table 11. Maintenance Activities on Rehabilitated Land – Ivanhoe North

NATURE OF TREATMENT	Area Treated (ha)		Comment/control treatment detail	strategies/
	Report Period	Next Period		
Additional erosion control (drains re-contouring, rock protection)	1.6	0.5	Installation of mid-slope contour banks and extra sediment dam capacity	
Re-covering (detail-further topsoil, subsoil sealing etc)	0	0	nil	
Soil Treatment (detail-fertiliser, lime, gypsum etc)	0	5	Bio solid and mulch trial	
Treatment/Management (detail-grazing, cropping, slashing etc)	0	0		
Re-seeding/Replanting (detail-species density, season etc)	1.6	0.5	Re seeding over new contour banks and sediment dam walls	
Adversely Affected by Weeds (detail-type and treatment)	0	0	NIL	
Feral animal control (detail – additional fencing, trapping, baiting etc)	0	0	NIL	

5.3 Rehabilitation Monitoring

Annual rehabilitation monitoring is undertaken at Ivanhoe North as a way to track, document and report on the success and performance of rehabilitation activities against the overall rehabilitation objectives for the site.

The monitoring programme involved the utilisation of the CSIRO developed Ecosystem Function Analysis (EFA) tool (Tongway & Hindley, 2004), vegetation monitoring components, and the AECOM developed Visual Monitoring Tool.

The EFA methodology created indices based on simple field indicators that reflect the measured variables of stability, water infiltration and nutrient cycling, in turn monitoring the functional status of the landscape. Utilising the EFA method, scientifically robust data is provided on the base sites, which when compared to the data collected from analogue sites, accurately reflects if the site is on a trajectory towards a sustainable ecosystem.

The purpose of the analogue sites is to represent as close as possible the proposed vegetation characteristics of the revegetation areas. The analogue site also provides data on the long-term goal for the revegetation area. Assessing the analogue sites is an integral part of monitoring rehabilitation and is used to generate a “band” of values depending on

seasonal effects as well as stochastic events like storms, droughts and fire. In addition, data recording the response and recovery dynamics to stochastic disturbances of the analogue site would provide a test of the resilience of a rehabilitated site (rate of recovery of function after specified disturbance).

In 2013 rehabilitation monitoring continued to be undertaken by AECOM.

The monitoring program currently includes seven transects, comprising four transects in rehabilitated areas and three analogue transects.

The existing four monitoring transects (IVN A1, IVN A2, IVN A3 and IVN R1) were re-surveyed during the 2013 monitoring event. An additional three rehabilitation transects (IVN R2, IVN R3 and IVN R4) were also established at this time and surveyed for the first time.

The topographic position of the study transects within the landscape is as follows:

- IVN A1 (established in 2010): located mid slope in a gently sloping area;
- IVN A2 (established in 2012): located on the upper slope in an area with a steeper gradient;
- IVN A3 (established in 2012): located on the lower slope in a gently sloping are;

- IVN R1 (established in 2011): located mid slope in a relatively flat area of the rehabilitated landform;
- IVN R2 (established in 2013): located on the upper slope of the rehabilitated landform;
- IVN R3 (established in 2013): located on the upper slope of the rehabilitated landform; and
- IVN R4 (established in 2013): located on the upper slope of the rehabilitated landform (**Table 12 and Figure 7**).

Table 12. Study Transects of Rehabilitation Monitoring Program

Transect	Type	Established
Transect 1 (IVN R1)	Rehabilitation	2013
Transect 2 (IVN R2)	Rehabilitation	2013
Transect 1 (IVN R3)	Rehabilitation	2013
Transect 2 (IVN R4)	Rehabilitation	2013
Analogue 1 (IVN A1)	Analogue	2010
Analogue 2 (IVN A2)	Analogue	2010
Analogue 3 (IVN A3)	Analogue	2012

5.3.1 Landscape Function Analysis

5.3.1.1 Landscape Organisation

The IVN R2, IVN R3 and IVN R4 sites returned comparable LOIs that were in the low-moderate range (0.27-0.37).

Rehabilitation at these sites was recent and the landscape organisation was driven by the trough and bank structure of soil that was still very prominent.

Despite the increase observed in 2012, the LOI at IVN R1 dropped back to a very low value of 0.02, which reflects the unsuccessful establishment of perennial ground cover at this site. In contrast to the other rehabilitation transects, IVN R1 is established in a flatter area lacking the trough and bank structure promoting the retention of resources and the gradual establishment of ground cover.

Overall, the landscape organisation at all rehabilitation sites poorly compare with that observed in analogue sites (where LOIs are comprised within 0.66-0.81). In the case of IVN R2, IVN R3 and IVN R4 this performance is explained by the young age of rehabilitation, and the LOIs at these sites are expected to increase in the coming years as the troughs trap resources and promoting the establishment of ground cover in larger areas. However, the situation appears different for IVN R1 where monitoring over the last three years indicates that ground cover is failing to establish (still >90% of bare ground recorded in 2013).




Figure 7. Monitoring Transect Locations at Ivanhoe North Colliery

5.3.1.2 Soil Surface Condition

Soil stability is satisfactory at IVN R1 and IVN R4 (i.e. stability index comprised within 40-60%) but is poor at IVN R2 and IVN R3 (i.e. index <40%). However, all sites have stability indices below 45% whereas the corresponding analogue sites returned indices of at least 63% (and up to ~78%). Stability in the rehabilitated landform is evidently limited by the lack of perennial vegetation cover, and evidence of active erosion is starting to materialise throughout the site.

Infiltration properties at all rehabilitation sites are poor with all indices <30%, while infiltration indices at analogue sites are all comprised between 40 and 50%. Here again the lack of vegetative cover is the principal limiting factor to the infiltration capacities of the soil. Generally, the infiltration properties of soils are related to their aggregation characteristics, with highly aggregated soils having increased pore space and higher infiltration potential (USDA 2008). Vegetation cover (ground cover and woody vegetation) largely contribute to the amount of organic matter present in the soil profile, which is positively correlated to the development of soil aggregates.

Further, the soil condition report prepared by SESL (2012) indicated that the soil composition comprises of a gravel, clay texture. Despite the sandy/gravelly nature of the top layer of the soil profile, the red/brown clay dominating the lower horizons limits the infiltration capacity of the soils. In contrast, soil composition at woodland analogue sites is comprised of a brown loam (SESL, 2012).

The lack of vegetative cover also implies very low nutrient cycling at all rehabilitation transects (indices <14%), and in this regards their performance is also very poor in comparison to the analogue areas (where nutrient cycling indices are comprised within 29-43%). No organic matter is currently returned to the system in the form of litter. However, it is noted that the nutrient cycling index is the most sensitive index of rehabilitation success as it is often non-existent in the early years of rehabilitation, and it usually takes a number of years until scores improve (Tongway et al, 1998).

No soil treatment was carried out in the reporting period. Organic fertiliser and bio solid trials are proposed for 2014 reporting period.

5.3.2 Vegetation Dynamics

Bare ground is largely dominating the rehabilitation areas across the site, and litter is absent. The poor ground vegetative cover at

the site may be related to the poor infiltration properties of the soil as identified in the soil surface assessment, water not being stored in the ground and therefore not available for root uptake and plant growth, limiting the establishment of ground species. It is also possible that the species mix used in past rehabilitation activities at Ivanhoe lacked groundcover and understorey species. The increasing incidence of active erosion will also limit the ground cover establishment.

Due to the age of rehabilitation at IVN R2, IVN R3 and IVN R3, the lack of woody plants cannot yet be assessed as a performance indicator of rehabilitation success, and this will need to be monitored in future years. Despite an increase in woody plant density from 2012, the number of woody species counted at UVN R1 remains relatively low and trees are evidently struggling establish. The lack of organic matter and the poor infiltration and water retention properties of the soil are likely causes of poor vegetation establishment.

It is noted that below average rainfall occurred in the area in 2012 (refer to Figure 2), which would have been unfavourable to vegetation growth and establishment.

5.3.3 Disturbance

Ivanhoe North consisting of one large contiguous rehabilitated landform, disturbance factors are similar across all monitoring transect areas. The main disturbance factors impacting on the site include erosion, feral animal damage and weed incursion.

Erosion and grazing impacts from introduced herbivores (rabbits and goats) and kangaroos (considerable in places) evidently limit the potential for perennial ground cover and shrub and trees establishment. Indeed, it is known that rabbits and goats can decimate newly established plants (DITR 2006).

Feral goats have previously had a major effect on vegetation through soil damage and overgrazing of herbs and grasses, and browsing of shrubs and trees (DSEWPC, 2011a). High densities of feral goats can rapidly deplete an area of its vegetation and prevent regeneration, which can lead to an increased chance of soil erosion. The characteristic pawing of the ground by male goats and the hard hooves of the herd, breaks the soil crust and exposes the soil to erosive forces of water and wind. This reduces soil stability resulting in wind or water erosion (Jago, 1999). It is likely that the poor vegetation establishment (especially at IVN R1) is at least partially a result of the impacts by feral goats in the area.

Grazing and burrowing by rabbits can cause serious erosion problems, reduce recruitment and survival of native plants, and modify entire landscapes (DEC, 2011).

Active erosion is evident throughout the site, particularly in the form of rills and gullies. Based on the last three years of monitoring at IVN R1, erosion seems to be increasing at the site and deeper gullies are developing.

Finally, weeds occur throughout the site. Although their coverage is still relatively limited, there is potential for spread to take place and impact on the potential and quality of rehabilitation. Feral goats, for example, are a known vector of weed spread through seeds carried in their dung (DSEWPC, 2011). Although goats consume some weeds (spear thistle, etc.) it has been suggested that the abundance of woody weeds has increased due to the presence of feral goats (Parkes et al. 1996). Furthermore, the poor soil properties and lack of perennial soil cover and vegetation will tend to promote weeds growth, which are better and faster colonisers of degraded and fragmented environments.

A commitment to effective rehabilitation involves an on-going monitoring and maintenance. Areas being rehabilitated will be regularly inspected in and assessed against the long and short-term rehabilitation objectives. During regular inspections, aspects of rehabilitation to be monitored will include:

- Evidence of any erosion or sedimentation from areas with establishing vegetation cover;
- Success of tree and shrub plantings;
- Adequacy of drainage controls and any other installed surface water management feature;
- Presence/absence of weeds; and
- General stability of the rehabilitation site.

Where the rehabilitation success appears limited, maintenance activities will be initiated. These may include re-seeding and where necessary, the application of specialised treatments such as composted mulch to areas with poor vegetation establishment.

No time limit has been placed on post-mining rehabilitation monitoring and maintenance. Maintenance will continue until such time as the objectives are met.

At the completion of rehabilitation establishment, monitoring will be carried out to assess early rehabilitation success, identify the need for any remedial action and determine whether rehabilitation is likely to meet long-term objectives and mine closure criteria.

A dedicated monitoring system will be identified in order to assess effectiveness of implementation of the rehabilitation measures as well as to identify the need for corrective action as soon as required.

Post rehabilitation, sites will monitor rehabilitation areas to demonstrate progress towards the completion criteria. This will be achieved through:

- Annual rehabilitation inspections that evaluate the success of the rehabilitation operation and reviews the trajectory of the rehabilitation towards completion criteria determined for the closure domain; and
- Long-term rehabilitation monitoring which is scientifically based and evaluates the progress of rehabilitation towards fulfilling completion criteria and the statutory requirements that may apply to the site.

The annual rehabilitation will be carried out by the Site Environment & Community Officer and/or specialist consultant to check for risks that may impact the success of rehabilitation.

6. Activities Proposed in the Next AEMR Period

The activities proposed for the next reporting period are generally in accordance with the MOP and existing approvals and include:

- Continuation of rehabilitation monitoring at Ivanhoe North Ongoing using the LFA assessment tool;
- Continue site maintenance (weed spraying, erosion and sediment controls);
- Organic fertiliser and bio solid trials in 2012 rehab area;
- Continue consultation with stakeholders regarding rehabilitation and mine closure at Ivanhoe North; and
- Continued consultation with OEHL and EPA regarding modifications to the MOP and EPL.

Ivanhoe North Rehabilitation Project AEMR Plans

Appendix 1

**Environment Protection Licence No.
13063- Ivanhoe North**

Appendix 2



Centennial Coal